




350986

IEPA 52 12/1/83
PA-SI PROGRAM

1/28/86

L11580101		POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT PART 1 SITE INFORMATION AND ASSESSMENT		I IDENTIFICATION 01 STATE 02 SITE NUMBER ILD 000671073	
II SITE NAME AND LOCATION					
01 SITE NAME (Legal, common, or descriptive name, if all)			02 STREET, ROUTE NO. OR SPECIFIC LOCATION IDENTIFIER		
WASTE Hauling Inc			RR #8, Box 98		
03 CITY		04 STATE		05 ZIP CODE	06 COUNTY
Decatur		IL		62522	MAcon
07 COUNTY CODE		08 COUNTY DIST			
115		20			
09 COORDINATES LATITUDE		LONGITUDE			
39 48 50 0		089 04 30 0		HARRISTOWN, IL 75' Quad (156-D)	
10 DIRECTIONS TO SITE (Starting from nearest public road)					
40 acres in the SW 1/4 of the SW 1/4 of Section 23 and the NW 1/4 of the NW 1/4 of Section 26, Township 16 North, Range 1 East, Macon County					
III RESPONSIBLE PARTIES					
01 OWNER (if known)			02 STREET (Business, mailing, residential)		
MR JERRY Camfield			129 WYCKLES Road		
03 CITY		04 STATE		05 ZIP CODE	06 TELEPHONE NUMBER
Decatur		IL		62522	217 422 2715
07 OPERATOR (if known and different from owner)			08 STREET (Business, mailing, residential)		
SAME					
09 CITY		10 STATE		11 ZIP CODE	12 TELEPHONE NUMBER
					()
13 TYPE OF OWNERSHIP (Check one)					
<input checked="" type="checkbox"/> A PRIVATE <input type="checkbox"/> B FEDERAL <input type="checkbox"/> C STATE <input type="checkbox"/> D COUNTY <input type="checkbox"/> E MUNICIPAL <input type="checkbox"/> F OTHER <input type="checkbox"/> G UNKNOWN					
14 OWNER/OPERATOR NOTIFICATION ON FILE (Check all that apply)					
<input type="checkbox"/> A RCRA 3001 DATE RECEIVED <input type="checkbox"/> B UNCONTROLLED WASTE SITE (CERCLA 103 d) DATE RECEIVED <input checked="" type="checkbox"/> C NONE					
IV CHARACTERIZATION OF POTENTIAL HAZARD					
01 ON SITE INSPECTION			02 BY (Check all that apply)		
YES DATE: 10-20-72 NO MONTH DAY YEAR 03-20-85			<input type="checkbox"/> A EPA <input type="checkbox"/> B EPA CONTRACTOR <input type="checkbox"/> C STATE <input type="checkbox"/> D OTHER CONTRACTOR <input type="checkbox"/> E LOCAL HEALTH OFFICIAL <input type="checkbox"/> F OTHER (Specify)		
03 CONTRACTOR NAME(S)					
02 SITE STATUS (Check one)			03 YEARS OF OPERATION		
<input checked="" type="checkbox"/> A ACTIVE <input type="checkbox"/> B INACTIVE <input type="checkbox"/> C UNKNOWN			1973 Present BEGINNING YEAR ENDING YEAR		
04 DESCRIPTION OF SUBSTANCES POSSIBLY PRESENT KNOWN OR ALLEGED					
Sludges, Solvents, Asbestos Toxic, Corrosive, Infectious, Flammable, Hospital Wastes, Ignitable					
05 DESCRIPTION OF POTENTIAL HAZARD TO ENVIRONMENT AND/OR POPULATION					
Groundwater (population) Surface water (population, environment)					
V PRIORITY ASSESSMENT					
01 PRIORITY FOR INSPECTION (Check one if high or medium is checked, complete Part 2, West Information and Part 3, Description of Hazardous Conditions and Incidents)					
<input type="checkbox"/> A HIGH (inspection required promptly) <input checked="" type="checkbox"/> B MEDIUM (inspection required) <input checked="" type="checkbox"/> C LOW (inspect on time, verifiable basis) <input type="checkbox"/> D NONE (No further action needed, complete current disposition form)					
VI INFORMATION AVAILABLE FROM					
01 CONTACT		02 OF (Agency Organization)		03 TELEPHONE NUMBER	
Jerry Camfield		Owner / Operator		217 422 2715	
04 PERSON RESPONSIBLE FOR ASSESSMENT		05 AGENCY		06 ORGANIZATION	
Kenneth L Page		IEPA		HSCS	
		07 TELEPHONE NUMBER		08 DATE	
		217 782 6760		12 30 85 MONTH DAY YEAR	



I HIGHLY VOLATILE
J EXPLOSIVE
K REACTIVE
L INCOMPATIBLE
M NOT APPLICABLE

VI SOURCES OF INFORMATION	C	specific	reference	of	stat	sample	analysis	reports
---------------------------	---	----------	-----------	----	------	--------	----------	---------



POTENTIAL HAZARDOUS WASTE SITE
PRELIMINARY ASSESSMENT

PART 3 DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS

I IDENTIFICATION

01 STATE 02 SITE NUMBER

ILD 000 671073

II HAZARDOUS CONDITIONS AND INCIDENTS

01 ☒ A GROUNDWATER CONTAMINATION

03 POPULATION POTENTIALLY AFFECTED 2,500

02 ☐ OBSERVED (DATE _____)

04 NARRATIVE DESCRIPTION

☒ POTENTIAL

☐ ALLEGED

Unlined landfill that accepts special with possible hazardous constituents percolation into ground water

01 ☒ B SURFACE WATER CONTAMINATION

03 POPULATION POTENTIALLY AFFECTED 2500

02 ☐ OBSERVED (DATE _____)

04 NARRATIVE DESCRIPTION

☒ POTENTIAL

☐ ALLEGED

Leachate seeps and flows were observed entering a small unnamed tributary that flows into the Sangamon River

01 ☐ C CONTAMINATION OF AIR

03 POPULATION POTENTIALLY AFFECTED _____

02 ☐ OBSERVED (DATE _____)

04 NARRATIVE DESCRIPTION

POTENTIAL

ALLEGED

01 ☒ D FIRE/EXPLOSIVE CONDITIONS

03 POPULATION POTENTIALLY AFFECTED _____

02 ☐ OBSERVED (DATE _____)

04 NARRATIVE DESCRIPTION

☒ POTENTIAL

☐ ALLEGED

Landfill accepted some wastes with a low flash point

01 ☐ E DIRECT CONTACT

03 POPULATION POTENTIALLY AFFECTED _____

02 ☐ OBSERVED (DATE _____)

04 NARRATIVE DESCRIPTION

POTENTIAL

ALLEGED

01 ☒ F CONTAMINATION OF SOIL

03 AREA POTENTIALLY AFFECTED 40

02 ☐ OBSERVED (DATE _____)

04 NARRATIVE DESCRIPTION

☒ POTENTIAL

ALLEGED

On site contamination from the acceptance of special wastes

01 ☒ G DRINKING WATER CONTAMINATION

03 POPULATION POTENTIALLY AFFECTED 2,500

02 ☐ OBSERVED (DATE _____)

04 NARRATIVE DESCRIPTION

☒ POTENTIAL

ALLEGED

SEE A+B ABOVE

01 ☐ H WORKER EXPOSURE INJURY

03 WORKERS POTENTIALLY AFFECTED _____

02 ☐ OBSERVED (DATE _____)

04 NARRATIVE DESCRIPTION

POTENTIAL

ALLEGED

01 ☐ I POPULATION EXPOSURE/INJURY

03 POPULATION POTENTIALLY AFFECTED _____

02 ☐ OBSERVED (DATE _____)

04 NARRATIVE DESCRIPTION

POTENTIAL

ALLEGED



POTENTIAL HAZARDOUS WASTE SITE
PRELIMINARY ASSESSMENT
PART 3 DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS

I IDENTIFICATION

01 STATE 02 SITE NUMBER
IL 000671073

II HAZARDOUS CONDITIONS AND INCIDENTS (Continued)

01 ☐ J DAMAGE TO FLORA
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE _____) ☐ POTENTIAL ☐ ALLEGED

01 ☒ K DAMAGE TO FAUNA
04 NARRATIVE DESCRIPTION (Include name(s) of species)

02 ☐ OBSERVED (DATE _____) ☒ POTENTIAL ☐ ALLEGED

From Leachate seeps that enter the Sangamon River, Leachate has hazardous constituents

01 ☐ L CONTAMINATION OF FOOD CHAIN
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE _____) ☐ POTENTIAL ☐ ALLEGED

01 ☒ M UNSTABLE CONTAINMENT OF WASTES
(Spills, runoff, standing liquids, leaking drums)

02 ☒ OBSERVED (DATE _____) ☐ POTENTIAL ☐ ALLEGED

03 POPULATION POTENTIALLY AFFECTED UNKNOWN

04 NARRATIVE DESCRIPTION

Leachate seeps and flows into unnamed tributary that flows into the Sangamon River

01 ☒ N DAMAGE TO OFFSITE PROPERTY
04 NARRATIVE DESCRIPTION

02 ☒ OBSERVED (DATE _____) ☐ POTENTIAL ☐ ALLEGED

This is a much a nuisance as actually damage, Wind blown litter and debris onto off site property

01 ☐ O CONTAMINATION OF SEWERS STORM DRAINS WWTPs
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE _____) ☐ POTENTIAL ☐ ALLEGED

01 ☒ P ILLEGAL/UNAUTHORIZED DUMPING
04 NARRATIVE DESCRIPTION

02 ☒ OBSERVED (DATE _____) ☐ POTENTIAL ☐ ALLEGED

Accepting special wastes in violation of Chapter 7 of the Illinois Pollution Control Board Rules and Regulations on Solid Waste

05 DESCRIPTION OF ANY OTHER KNOWN POTENTIAL OR ALLEGED HAZARDS

III TOTAL POPULATION POTENTIALLY AFFECTED 2,500

IV COMMENTS

V SOURCES OF INFORMATION (Cite specific references g state file sample analysis reports)

EXECUTIVE SUMMARY

Waste Hauling, Inc , formerly McKinney No 2 Landfill, L1158010001, ILD000671073 A 40 acre site in the SW $\frac{1}{4}$ of the SW $\frac{1}{4}$ of Section 23 and the NW $\frac{1}{4}$ of the NW $\frac{1}{4}$ of Section 26, Township 16 North, Range 1 East in Macon County

The initial application for a permit for this site was submitted in March of 1972 to cover approximately 40 acres Due to the location and nature of the site (sandy soils and partial flood plain location) and the desired operation (cover excavation then area fill), the original operating permit only authorized approximately 5 acres in the northeast corner of the property A supplemental permit was issued in February of 1974 allowing use of the remaining 35 acres Operation did not start in the 35 acre tract until the Fall of 1979

The site is located less than one-quarter mile south of the Sangamon River Agricultural land uses are predominant around the site The closest residence is less than one-quarter mile south of the site

The groundwater monitoring program at this site consists of one well (G101) in the Northwestern part of the site The well is approximately 20 feet deep and screened from about 8.5 feet to 18 feet below ground

Residents in the area of the landfill complained of a bad odor in their private wells The private well of William Koretke was sampled on December 19, 1979 at 10:10 A.M. to determine the source of the odor (septic in nature) No evidence was found to support the allegation that the landfill was the source of contamination The septic sewer of the William Koretke residence was believed to be his source of contamination (odor)

Leachate seeps and flows have been an on-going problem Leachate seeps into a small unnamed tributary that flows into the Sangamon River Surface water contamination is possible with this problem Special Wastes were accepted in violation of Chapter 7 of the Illinois Pollution Control Board Rules and Regulations on Solid Wastes Some special wastes accepted in violation were Hospital Pathological Wastes surgical gloves, oxygen masks, disposable respirator tubing, I.V. tubing, medicated enema apparatuses and used specimen containers

Other operational problems are lack of daily cover, lack of intermediate cover, lack of final cover, large amounts of wind-blown litter, erosion and flooding and ponded water on-site

No known hazardous wastes were accepted at this landfill, but special wastes with hazardous constituents were accepted The landfill is unlined and lies within the Sangamon River flood plain Ponded water and flooding has been observed on-site With water ponding on-site, leachate flows freely, potentially affecting surface and groundwater

With the potential for groundwater and surface water contamination (but no known contamination to this day), this site is assigned a medium priority

KLP cm 4/30